

Amendments to the Specification

Please amend paragraph [00035] on pages 12 and 13 as follows:

[00035] As shown in Figure 9, a compression arm 82, which is typically fitted with a pair of adjustment screws 83, is provided on the probe base 67 and engages the probe pins 36. The adjustment screws 83 can be manipulated to adjust the compression arm 82 against the probe pins [[83]] 36 and adjust the contact angle of the probe pins [[83]] 36 with respect to the test points (not shown) on the LCD panel (not shown) during testing of the LCD panel.